



This is the north side of the building where we installed the emergency egress staircase. The front corner is where the electric power lines are attached to the building from the service pole.



Power line connections to the building in the front corner.



Better view of the power supply lines coming in and attaching to the building





Northeast view of the roof top area and the recessed tile mansard that has been on the building prior to 1952.





This is the south section of the building where there is a parapet wall on the roof that separates the two areas. So it would not be feasible to try to put the lift on this end as there is no access to that deck area.



This currently is the front of the building showing the open air roof area. The railing has been added on the deck upstairs. The canvas awnings are under production and not installed yet but they are planned on the front as well.



Interior spiral staircase which exits on the deck where there appears to be a small enclosure on the deck area.





Inside service area



Another view of spiral staircase



This is the retail section where the unisex restroom which services everywhere.