









REVISION NUMBER 5				REVISION NUMBER 4				REVISION NUMBER 3				REVISION NUMBER 2				REVISION NUMBER 6			
ADD FLORIDA APPROVAL LOGO				REMOVE DRAWING REFERENCE P-1050198				REVISED BOLT NOTE AT GIRTS TO PUT LEG UP				EDIT FASTENER COLOR FROM BIRCH				ADDED THE FBC CORROSION NOTE.			
24519				11/11/19				06/15/17				01/03/12				09/16/26			
REMOVE ALL LITE*PANEL PART NUMBERS				P-080884 REPLACE WITH WCB045,				VIEW "F" TO PUT LINES IN CORRECT				WHITE TO COOL IVORY WHITE, WHICH				NF			
IN CHART AND REPLACE WITH PART				WCB046 AND WCB056 REMOVE P-105088				ORDER. WORDING REMAINED AS IS.				IS AS VISION PROVIDES.				DWBY CHKO			
BSN				JLH				PW				BJF				RLB			
PLAN CLEAN UP, #23150				ADDED TO DEFECT 17133.															



BUTLERIB LITE*PANLS			OPERATION CODE
VARIABLE LENGTH	BRLP_	SQUARE CC2	35
	BRLP_	SQUARE CC1	35
	BRLP_	THRU 1:12 MITER CC2	EE
	BRLP_	THRU 1:12 MITER CC1	EE
	BRLP_	4:12 MITER CC2	FF
	BRLP_	4:12 MITER CC1	FF



- GENERAL NOTES:
1. ALL SPLICES MUST BE AT GIRTS. IF NOT AT A STANDARD GIRT LOCATION THEN AN ADDITIONAL GIRT MUST BE ADDED.
 2. FOR VERTICAL TRANSITION TO OTHER BUTLER WALLS SEE THE APPROPRIATE DRAWING.
 3. SEE GENERAL WALL INSTALLATION DRAWINGS FOR REINFORCEMENT CLIP, PANEL CLOSURE PART NUMBERS AND WALL PANEL INSTALLATION PROCEDURES.

6

** FOR INSTALLATION IN AREAS WITHIN 3000 FEET OF A SALTWATER COASTLINE, FASTENERS ARE CORROSION RESISTANT AS PER THE FLORIDA BUILDING CODE, SECTION 1711.



BUTLERIB II WALL LITE*PANEL INSTALLATION			
DRAWN BY	CHECKED BY	GROUP NUMBER: 26-029-02	
JPV	BJF		
FIRST RELEASE DATE	REVISION DATE		
01/21/10	09/16/26		
		B	P-080889 06