





MORTON BUILDINGS
CONSTRUCTION PROCEDURE MANUAL


MB 910 ENTRY DOOR FASTENER LOCATION

(HINGE SIDE SHOWN -- FASTENER LOCATIONS ARE SAME ON BOTH SIDES)



Allen N. Reeves
2 AUG. 2021

OUTSWING DETAILS



INSWING DETAILS

