

L. Roberto Lomas P.E.

208 7th Avenue
Indialantic, FL 32903
434-688-0609
rlomas@lrlomaspe.com

Engineering Evaluation Report

Report No.: 514887B

Manufacturer: Reilly Windows & Doors
901 Burman Blvd.
Calverton, NY 11933

Product Line: M1, M2, M3, M4 & MZ1 Horizontal Mullion

Compliance:

The product listed herein complies with requirements of the current Florida Building Code.

Supporting Technical Documentation:

1. Approval document: drawing number 08-03738 Revision B, prepared, signed and sealed by Luis Roberto Lomas P.E.
2. Mullion analysis, report numbers 514887-1B through -3B, per AAMA 450 option 3, prepared, signed and sealed by Luis Roberto Lomas P.E.

Limitations and Conditions of use:

- Design pressure: Refer to charts in approval document
- Mullion span: Refer to charts in approval document
- This product is not rated to be used in the HVHZ.
- This product is impact resistant and does not require impact protection in wind borne debris regions up to wind zone 3.
- Mullion material to be Steel.
- Fenestration units attached to mullion must have their own separate approval.
- Design pressure of mulled units shall be controlled by the lesser design pressure of the assembly components; the mullion or the individual units.

Installation:

Units must be installed in accordance with manufacturer's installation instructions and approval document, 08-03738 Revision B.

Certification of Independence:

Please note that I do not have nor will acquire a financial interest in any company manufacturing or distributing the product(s) for which this report is being issued. Also, I do not have nor will acquire a financial interest in any other entity involved in the approval process of the listed product(s).

