

L. Roberto Lomas P.E.

208 7th Avenue
Indialantic, FL 32903
434-688-0609
rlomas@lrlomaspe.com

Engineering Evaluation Report

Report No.: 515216A

Manufacturer: **Reilly Windows & Doors**
 901 Burman Blvd.
 Calverton, NY 11933

Product Line: X-Mullion - Impact

Compliance:

The product listed herein complies with requirements of the current Florida Building Code.

Supporting Technical Documentation:

1. Approval document: drawing number 08-03957 Revision A, prepared, signed and sealed by Luis Roberto Lomas P.E.
2. Mullion Analysis, report number 515216-1A Per AAMA 450, Option 3, prepared, signed and sealed by Luis Roberto Lomas P.E.

Limitations and Conditions of use:

- Design pressure: See charts in installation drawing.
- This product is not rated to be used in the HVHZ.
- This product is impact resistant and does not require impact protection in wind borne debris regions up to wind zone 3.
- Mullion material to be Steel.
- All windows mulled to this product must be manufactured by Reilly Windows & Doors and must have their own Product Approval.

Installation:

Units must be installed in accordance with manufacturer's installation instructions and approval document, 08-03957 Revision A.

Certification of Independence:

Please note that I do not have nor will acquire a financial interest in any company manufacturing or distributing the product(s) for which this report is being issued. Also, I do not have nor will acquire a financial interest in any other entity involved in the approval process of the listed product(s).

