

STRUCTURAL SOLUTIONS, P.A.*

Structural Engineering ■ Investigations ■ Consulting

April 7, 2015

Mr. Brandon Gentle
Entrematic
165 Carriage Court
Winston-Salem, NC 27105

Re: Salt Spray Testing for Entrematic / Amarr Garage Doors
Architectural Testing, Inc. Report # C5463.01-106-18 dated 4/3/2013
Florida Product Approval # FL 7152-R5
Project No. 15-001

Dear Mr. Gentle:


I have reviewed the report for the Salt Spray test performed by Architectural Testing, Inc. Refer to their Report # C5463.01-106-18 dated 4/3/2013, for the tests conducted 1/29/2013 through 3/25/2013. (This report supersedes Architectural Testing, Inc. Report # A7420.01-106-18 dated 4/12/2011).

The above referenced Architectural Testing report states the following:

- The test was conducted in accordance with Miami Dade County Checklist #0220, ASTM D1654-08, and ASTM B117-11
- There was no red rust present on the coated steel test panels supplied by Entrematic / Amarr, while the G-90 coated steel control samples displayed heavy corrosion over the entire specimen face.
- The test was witnessed and certified by Gary T. Hartman, PE (FL PE #73227)

Please use this letter to update my Evaluation Report(s) for Florida Product Approval # FL 7152-R5 as applicable.

Sincerely,



STRUCTURAL SOLUTIONS, P.A.*
Thomas L. Shelmerdine, PE
Florida PE #48579
President