







# Giller & Giller, Inc.

The Giller Building 975 Arthur Godfrey Road Miami Beach, Florida 33140 (305) 538-6324 fax/modem (305) 538-5921 Reg. #AA C001364



August 30, 2018

Mr. Chip Sellers Accessibility Council Florida Building Commission Dept. of Business & Professional Regulation 2601 Blair Stone Rd. Tallahassee, FL 32399

### Re: Life House Renovations - Miami Beach 321 Collins Ave. Miami Beach, FL 33139

Mr. Sellers:

Per your communications with Steve Bernard of this office, Giller & Giller Inc. has been retained by the owner of the above referenced project to assist their architect, Seven Ave. Design Studio LLC in obtaining an accessibility waiver for this project.

The project is an existing 2 story hotel building constructed in the 1930's and is a contributing building in the Ocean Beach Historic District. Typical of the Miami Beach historic structures, the project has constraints in all of its renovation aspects.

I have attached the Cost Analysis from the general contractor, Happy Home Services of SWFL, Inc. which shows total project cost of \$779,220.

The proposed project scope of work will include making the 1<sup>st</sup> floor accessible in conformity with the Florida Building Code and the ADA. Work will include: a new ramp, new accessible room doors, two accessible rooms, and accessible public toilets. The total cost of this accessibility work is \$65,72967 according to the contractor's cost analysis. This amounts to 8.3% of the construction cost.

In order to provide accessibility on the 2<sup>nd</sup> floor, vertical accessibility will be required. The contractor has provided a cost breakdown to add an elevator, make the necessary structural changes, provide shaft enclosure and roofing, and provide upgrades to the electrical to the building for a total cost of \$127,140. This 16.3% of the total construction cost.

## Giller & Giller, Inc.

In aggregate, the total cost of full accessibility improvements for both the 1<sup>st</sup> and 2<sup>nd</sup> floors will be \$192,869. This is almost 25% of the construction cost. Since this exceeds the maximum obligation of 20% of the construction budget, the owner has elected to seek a waiver for the vertical accessibility to the 2<sup>nd</sup> floor.

This letter and the contractor's cost breakdown support the application previously filed with you.

If you have any questions, please contact me.

Sincerely,

Ira D. Giller, A.I.A. President

#### Happy Home Services of SWFL Inc, Its Subsidiaries and Holdings

3702 W Promontory Drive, Beverly Hills, FL 34465 Miami Area Lic Numbers CGC 1508774- CCC 1326397 Alan Krinsky, President 352-566-0139

#### Life House South Beach (Jazz Hotel) Cost Analysis and Structure 321 Collins Ave., Miami Beach, FL33139

COST PLUS												
Bathroom		Labor	Material	Admin	Conditions	Profit	Total					
Tile	\$	700.00 \$	737.64		contactions	mont	\$ 1,437.64	Same	Ś	1,437.64		
Electrical	\$	200.00 \$	54.16 \$	10.17	\$ 10.17 \$	40.67	\$ 315.16	Increase	\$	437.31		
Lighting	Ś	84.03 \$	30.00 \$		\$ 4.56 \$		\$ 141.40		ŝ	235.21		
Toilet	\$	40.00 \$	11.00 \$		\$ 2.04 \$		\$ 63.24		Ś	63.24		
Shower Drain	\$	32.41 \$	50.04 \$	3.30					Ś	102.24		
Shower valve and head kit	\$	150.00 \$	356.19 \$		\$ 20.25 \$		\$ 627.68		Ś	784.21		
Shower glass	Ś	75.00 \$	359.54 \$	17.38	\$ 17.38 \$	69.53	\$ 538.83		ŝ	538.83		
Door Lock	\$	15.00 \$	50.07 \$		\$ 2.60 \$				Ś	80.69		
Curtains	\$	- \$	- \$		\$ - \$		\$ -		ŝ		New Item Venting Fan	
Accessories (TP Holder, Floating Shelf, Soap Dispenser, 2 Hooks)	\$	32.41	Ś	1.30			\$ 40.19	Same	ŝ	40.19		
Saddle	\$	- \$	38.52 \$	1.54				Same	ŝ	47.76		
Re-wire Ceiling light	\$	<b>35.00</b> \$	39.11 \$		\$ 2.96 \$		\$ 91.90		Ś	195.35		
Ceiling Trim & Paint	\$	40.00 \$	46.08 \$	3.44			\$ 106.74		Ś	106.74		
Waterproofing	\$	15.00 \$	25.18 \$	1.61	\$ 1.61 \$	6.43	\$ 49.82	Same	\$	49.82		
Threshold	Ś	35.00 <b>\$</b>	30.00 S	2.60	\$ 2.60 \$	10.40	\$ 80.60	Same	Ś	80.60	Building Total Average Bedroom	
	\$	1,453.85 \$	1,827.53 \$	73.75	\$ 73.75 \$	295.00	\$ 3,723.88	-	\$	4,409.81	\$	114,655.06
Room		,	, ,				,		•	,	·	
Bedding Structure Transport into building	\$	-	\$	-	\$ - \$	-	\$ -	Increase			This is not assigned yet	
Bedding structure assembly	\$	- \$	- \$	-	\$ - \$	-	\$ -	Increase			<b>.</b> .	
Installation of Mattresses in room	\$	35.00	\$	1.40	\$ 1.40 \$	5.60	\$ 43.40	Same				
Screens For Windows	\$	- \$	- \$	-	\$ - \$		\$-	Increase	\$	2,000.00	New Windows apx est.	
Remove AC patch interior (Not Exterior)	\$	139.00 \$	51.19 \$	7.61	\$ 7.61 \$	30.43	\$ 235.84	Increase	\$	298.53		
Frame Rear Wall	\$	<b>194.46</b> \$	142.43 \$	13.48	\$ 13.48 \$	53.90	\$ 417.74	Same	\$	417.74		
Drywall & Painting (Exterior wall and bunk headboard walls)	\$	248.48 \$	167.40 \$	16.64	\$ 16.64 \$	66.54	\$ 515.69	Different	\$	492.32	New Scope	
Ply Coat Ceiling (8" beadboard)	\$	259.28 \$	329.20 \$	23.54	\$ 23.54 \$	94.16	\$ 729.72	Different	\$	829.83	New Scope	
Ply Coat All Walls (4" beadboard)	\$	259.28 \$	529.20 \$	31.54	\$ 31.54 \$	126.16	\$ 977.72	Different	\$	793.26	New Scope	
Wood Trim Design Walls (vertical & horizontal casing, door casing, window casing, locker fills)	\$	259.28 \$	<b>248.16</b> \$	20.30	\$ 20.30 \$	81.19	\$ 629.23	Same	\$	629.23	New Scope	
Paint all Ply and design wood	\$	129.64 \$	94.30 \$	8.96	\$ 8.96 \$	35.83	\$ 277.69	Different	\$	373.21	New Scope	
Locker Structure Build	\$	275.00 \$	<b>194.51</b> \$	18.78	\$ 18.78 \$	75.12	\$ 582.19	Same	\$	582.19		
Locker Structure Install	\$	140.00 \$	51.84 \$	7.67	\$ 7.67 \$	30.69	\$ 237.88	Same	\$	237.88		
Shipping Items from shop to site	\$	20.00 \$	- \$	0.80	\$ 0.80 \$	3.20	\$ 24.80	Same	\$	24.80		
Gutting (removing old items and materials)	\$	140.00 \$	23.00 \$	6.52	\$ 6.52 \$	26.08	\$ 202.12	Increase	\$	253.23	Difference caused by Dump Fees	
Construct Wing Wall	\$	64.82 \$	46.96 \$	4.47	\$ 4.47 \$	17.88	\$ 138.61	Same	\$	138.61		
Construct plumbing wall behind sinks	\$	64.82 \$	46.96 \$	4.47	\$ 4.47 \$	17.88	\$ 138.61	Increase	\$	296.90		
Electrical	\$	600.00 \$	286.27 \$		\$ 35.45 \$			Increase	\$		New Feeds to Room	
Rough Plumbing	\$	160.00 \$	41.18 \$	8.05	\$ 8.05 \$	32.19	\$ 249.46	Same	\$	249.46		
P-trap	\$	<b>15.00</b> \$	47.37 \$		\$ 2.49 \$		\$ 77.34	Same	\$	77.34		
Faucet	\$	<b>64.82</b> \$	197.14 \$		\$ 10.48 \$	41.91	\$ 324.83	Same	\$	324.83		
Sink	\$	60.00 \$	256.00 \$	12.64	\$ 12.64 \$	50.56	\$ 391.84	Same	\$	391.84		
NEW AC (Sub)** (includes all room and rooftop units + condensate/refrigerant lines, excludes electric	\$	1,766.00	\$		\$ 70.64 \$		\$ 2,189.84		\$	2,189.84		
Entry Door Saddle	\$	35.00 \$	38.52 \$	2.94	\$ 2.94 \$			Same	\$	91.16		
Bathroom Door with standard hinges	\$	162.05 \$	185.00 \$	13.88	\$ 13.88 \$	55.53	\$ 430.34	Same	\$	430.34		
Door Stop	\$	10.00 \$	15.00 \$	1.00	\$ 1.00 \$	4.00	\$ 31.00		\$	31.00		
New entry door core with 2 spring hinges and 1 standard hinge (prepped for OFCI hardware)	\$	97.23 \$	207.40 \$	12.19	\$ 12.19 \$	48.74	\$ 377.74	Different	\$	440.87	Building Room Total Average	
	\$	5,199.16 \$	3,199.03 \$	335.93	\$ 335.93 \$	1,343.71	\$ 10,413.75		\$	13,028.70	\$	338,746.20
								-				
Hallways based on 1400 sq. feet		Labor	Material	Admin	Conditions	Profit	Total					
Ceiling (hard with supports)	\$	1,120.00 \$	1,027.84 \$	85.91	\$ 85.91 \$	343.65	\$ 2,663.32	Different	\$	3,869.87	Scope Change	
Ceiling Finishing	\$	1,050.00 \$	397.51 \$	57.90	\$ 57.90 \$	231.60	\$ 1,794.91	Same	\$	1,794.91		
Gut (Removal of existing)	\$	500.00 \$	160.00 \$	26.40	\$ 26.40 \$	105.60	\$ 818.40	Different	\$	1,472.34	Dump Charges Changed	
AC (Done by Sub) 2 per floor**	\$	4,096.00	\$	163.84		655.36	\$ 5,079.04	Same	\$	5,079.04		
Electric General Lights	\$	1,100.00 \$	300.00 \$	56.00	\$ 56.00 \$	224.00			\$	1,736.00	Kept same price but points are changing	
Wall Repair removal of texture with painting	\$	2,100.00 \$	790.51 \$	115.62	\$ 115.62 \$	462.48		Different	\$	5,000.00	No Idea on New Scope	
	ć	0.000 00 0	2 675 96 6	FOF 67	¢ 505.67 ¢	2 022 70	¢ 15 675 01		÷	10 053 10		

505.67 \$

2,022.70 \$ 15,675.91

\$

\$

18,952.16

18,952.16

9,966.00

\$

2,675.86 \$

505.67 \$

Average Hall is 700 sq. feet o 1400 sq. feet total

Average sq. Feet of Hall Wall 2 sides/2 floors 4480 total

Kitchen	Labor		Materials		Admi	in	Conditions		Profit		Tota	al						
Baseboard	\$	74.82	\$	234.68	\$	12.38	\$ 1	2.38	\$	49.52	\$	383.78	3 Same	\$	49.52			
FRP and Adhesive	Ś	1,625.18	\$	1,449.16	Ś	122.97	\$ 12	22.97	\$	491.89	\$	3,812.18	3 Same	\$	3,812.18			
Washable Tiles	\$	162.05	\$	569.75	\$	29.27	\$ 2	29.27	\$	117.09	\$	907.43	3 Same	\$	907.43			
Door	Ś	2,278.00	\$	834.75	Ś	124.51	\$ 12	24.51	\$	498.04	\$	3,859.81	L Same	\$	3,859.81			
Materials for door			\$	227.90	\$	9.12	\$	9.12	\$	36.46	\$	282.60	Different	\$	782.69	Scope Chang	es	
Exterior steps/ramp/hand rail			\$	6,215.00	\$	248.60	\$ 24	18.60	\$	994.40	\$	7,706.60	Different	\$	9,639.62	Scope Chang	es	
Electric														\$	11,362.51	Main Power	Scope Change, Maybe lower	
Plumbing														\$	4,952.90	Drainage Tie-	-in Changes	
Kitchen Wall Framing														\$	2,500.00		Ū	
														\$	37,866.66	-	\$	37,866.66
ADA Bathrooms Raising Floor	This is a	price based o	n verv basic	alterations	realize	d								\$	15,000.00			
ADA Bedroom Increases	This is a price based on very basic alterations realized Please Note some of bedroom is covered under room budget							Ś	4,000.00									
Sprinkler and Alarm System	i icuse ii	ote some or t		Jorerea and		in buuget								ŝ	120.000.00			
Stair Rails	No Defir	No Defined Scope this is not a firm price							ŝ	7,000.00								
Lobby	No Defined Scope this is not a firm price							ŝ	25,000.00									
Roof														ŝ	40,000.00			
Closets	There is closest etc. that will need minor workings							Ś	1.000.00									
Stair area repair	The areas around the stairs have extensive damage							\$	5,000.00									
Repair Front Poarch														\$	3,000.00			
Front Door	No Curre	ent Bids as of	this budget	exercise										Ś	4.000.00			
Front Windows	No Curre	ent Bids as of	this budget	exercise										\$	10,000.00	New Scope		
Building Painting with stucco repair														\$	35,000.00			
														\$	269,000.00	-	\$	269,000.00
This is an apx building total not including FFE or equipment																	\$	779,220.08
														Total			\$	779,220.08

## Life House South Beach (Jazz Hotel) Cost Analysis and Structure

#### 321 Collins Ave., Miami Beach, FL33139

ADA IMPROVEMENTS PROPOSED:		
ADA Bathrooms Raising Floor	This is a price based on very basic alterations realized	\$ 15,000.00
ADA Bedroom Increases	Please Note some of bedroom is covered under room budget	\$ 4,000.00
ADA Public Toilets (2)	Based on design provided and taking into account normal schedule 10 items and fixtures	\$ 12,000.00
ADA Rooms& Baths (2)	Based on current design	\$ 17,542.14
ADA Ramp & Railing	Previously Bid	\$ 9,857.61
ADA Doors -1st floor rooms entry	Per Door Est 8 @541.24 each	\$ 4,329.92
ADA Doors @ lobby to ramp, ramp to laundry, ADA toilets	Waiting for Design basic electronic open door X2	\$ 3,000.00
TOTAL ADA IMPR	OVEMENTS PROPOSED	\$ 65,729.67
ADDITIONAL ADA WORK FOR VERTICAL ACCESSIBILITY:		

ADDITIONAL ADA WORKTOK VERTICAL ACCESSIBILITY.	
ADA Elevator	\$ 62,584.00
Elevator Structure - Foundation, shaft walls enclosure, roofi, roofing	\$ 49,571.00
ADA Electric Upgrades - Additional service & power distribution	\$ 14,985.00
TOTAL ADA WORK FOR VERTICAL ACCESSIBILITY	\$ 127,140.00
TOTAL ADA IMPROVEMENTS	\$ 192,869.67

8.3% OF CONSTRUCTION COST

16.3% OF COSNTRUCTION COST

24.6 % OF CONSTRUCTION COST EXCEEDS MAX. 20% REQD.