

From: David Wiles [mailto:dwiles@cityofcocoabeach.com]
Sent: Tuesday, May 10, 2016 11:39 AM
To: Madani, Mo
Cc: Arlene Z. Stewart (azstewart@azsconsultinginc.com)
Subject: 5th Edition FBC, Mechanical - code section reference in error

Mr. Madani –

A colleague suggested I send the **following** to you in case it can be changed when glitch changes are made for HB535:

The 5th Edition FBC, Mechanical section 401.4 Item 2 references section “501.2.1” but, there isn’t a section “501.2.1” in the 5th Edition.

The 2010 FBC, Mechanical does contain section “501.2.1” which identical wording can be found in the 5th Edition in section 501.3.1.

Note:

*It appears this was missed in the ICC 2012 base code and carried through to the 5th Edition.
The ICC 2015 base code appears to have corrected this.*

Thank you,