#### Department of Business and Professional Regulation FLORIDA BUILDING COMMISSION 1940 North Monroe Street Tallahassee, Florida 32399-0772 Form FBC 2012-01 Request for Waiver

#### NOTICE TO WAIVER APPLICANTS

Please make certain you comply with the following:

- The person submitting the waiver request application as the Applicant MUST sign the application. Should you fail to do so, your application will be returned.
- If a licensed design professional (architect or engineer) has designed the project, his or her comments MUST be included as a part of this application.
- Be as explicit as possible. The more information provided to the Florida Building Commission, the more informed its decisions can be. If you are claiming financial hardship, please specify why and to what degree. Two estimates substantiating a claim for disproportionate cost must be included.
- Petitioners are strongly advised to participate in the Council's conference call, webinar or onsite meeting for application review. Sometimes pertinent facts are inadvertently omitted, or information provided/presented in the Request for Waiver application is not clear. Your participation in the meetings to answer questions will enhance the possibility of the waiver being approved, since the Council and the Commission will receive the most complete information from you. When we receive the completed application, we will send you a notice of the time, date, and place for both the Council and the Commission meetings.

#### Enclosed is a List of Required Information and the Request for Waiver application.

If you have any questions or would like additional information, please call the Codes and Standards Section at (850) 487-1824.

**Please mail** this application to the Department of Business and Professional Regulation at the address above. Include a copy of the application, photos where appropriate and drawings or plans on a CD in PDF format. NOTE: Please do not send files in CAD format but rather provide the files in pdf format.

FBC 2012-01 Request for Waiver

This application is available in alternate formats upon request. **LIST OF REQUIRED INFORMATION:** 

1. X Drawings that will clearly present your project and that identify the issue(s) that relate to the waiver you are requesting. As a minimum, the following drawings must be submitted:

- a. Project site plan if pertinent to the application
- b. 24" x 36" minimum size drawings
- c. Building/project sections (if necessary to assist in understanding the waiver request)
- d. Enlarged floor plan(s) of the area in question

2. \_\_\_\_X\_\_\_\_ When substantial financial cost of compliance is alleged, supporting cost estimates with quotes from at least two vendors or contractors and catalog information.

3. \_\_\_\_X\_\_\_ If you feel photographs and/or renderings are necessary for your presentation, provide legible color copies of the photographs and/or renderings on the CD with the application and plans in jpeg, tif or pdf format.

4. \_\_\_\_X\_\_\_ Please submit one hard copy of this application and attachments to the Florida Building Commission, Department of Business and Professional Regulation.

#### **General Information:**

a. Verbal Descriptions: Presentations may be to sight or hearing impaired persons; visual presentations should consider adequate verbal and text descriptions of charts and pictures.

Your application will be reviewed by the Accessibility Advisory Council. You will have the opportunity to answer questions and/or make a short presentation **not to exceed 15 minutes**. The Council will provide recommendations to the Florida Building Commission. The Commission will review the application- where you will have another opportunity to answer questions and /or give a short presentation **not to exceed 15 minutes**. The Commission will consider all information and the Council's recommendation before voting on the waiver.

This application is available in alternate formats upon request.

#### REQUEST FOR WAIVER FROM ACCESSIBILITY REQUIREMENTS OF CHAPTER 553, PART II, FLORIDA STATUTES

Your application will be reviewed by the Accessibility Advisory Council and its recommendations will be presented to the Florida Building Commission. You will have the opportunity to answer questions and/or make a short presentation, not to exceed 15 minutes, at each meeting. The Commission will consider all information presented and the Council's recommendation before voting on the waiver request.

#### 1. Name and address of project for which the waiver is requested.

Name:	_2501 Riverside Avenue Renovation
Address:	_2501 Riverside Avenue, Jacksonville, FL 32204
2. Name of A owner and w	applicant. If other than the owner, please indicate relationship of applicant to ritten authorization by owner in space provided:
Applicant's N	Name:Christopher P. Noel, AIA, LEED AP TTV Architects Inc
Applicant's A	Address:_115 East Forsyth Street, Jacksonville, FL 32202
Applicant's 7	Felephone:_904.798.8333   FAX:_904.798.8335
Applicant's I	E-mail Address: chrisn@ttvarch.com
Relationship	to Owner:Architect for Owner
Owner's/Ten	ant's Name:Scot and Alex Ackerman
Owner's Add	Iress:4072 Alhambra Drive West, Jacksonville, FL 32207
Owner's Tele	ephone:_904.399.3636 FAXNA
Owner's E-m	alex@ackermania.com
Signature of	Owner: AMM
3. Please che	ck one of the following:

[] New construction.

FBC 2012-01 Request for Waiver

[] Addition to a building or facility.

[X] Alteration to an existing building or facility.

[] Historical preservation (addition).

[] Historical preservation (alteration).

4. **Type of facility.** Please describe the building (square footage, number of floors). Define the use of the building (i.e., restaurant, office, retail, recreation, hotel/motel, etc.)

\_\_\_\_\_The facility is an existing 2-story brick building (non-historic) constructed in 1943 of approximately 3,748 square feet. The building use is Office.\_\_\_\_\_\_

5. Project Construction Cost (Provide cost for new construction, the addition, or the alteration): \_\_\_\_\_ The project Cost is estimated to be \$574,048\_for the alteration (not including the elevator)\_\_\_\_\_\_

6. **Project Status:** Please check the phase of construction that best describes your project at the time of this application. Describe status.

[X] Under Design [] Under Construction\*

[] In Plan Review [] Completed\*

\* Briefly explain why the request has now been referred to the Commission.

\_The project is currently in the Construction Documents phase.

7. **Requirements requested to be waived.** Please reference the applicable section of Florida law. Only Florida-specific accessibility requirements may be waived.

Issue

1:\_FL Accessibility Code, Section 201.1.1 Vertical Accessibility\_\_\_\_\_

FBC 2012-01 Request for Waiver

Issue		
2:	······	 
Issue		
3:		 

8. **Reason(s) for Waiver Request:** The Florida Building Commission may grant waivers of Florida-specific accessibility requirements upon a determination of unnecessary, unreasonable or extreme hardship. Please describe how this project meets the following hardship criteria. Explain all that would apply for consideration of granting the waiver.

[] The hardship is caused by a condition or set of conditions affecting the owner which does not affect owners in general.

[X] Substantial financial costs will be incurred by the owner if the waiver is denied.

Project involves the complete renovation, including existing site & all existing systems of an existing 2-story commercial building. Estimated renovation costs are significant and the estimated cost for the new elevator would make the project financially unfeasible.

[X] The owner has made a **diligent investigation** into the costs of compliance with the code, but cannot find an efficient mode of compliance. Provide detailed cost estimates and, where appropriate, photographs. Cost estimates must include bids and quotes.

Renovated building will house one Tenant on both floors with the new design locating all of the Common Public, Accessible spaces and areas on the first floor such as Conference Room, ADA Restrooms, Accessible Work Areas, and Accessible Breakroom. All of the first floor accessible spaces are then accessed by new ADA Ramp, enlarged door opening with new 36" wide door,

FBC 2012-01 Request for Waiver

and ADA parking spaces with sidewalk on the exterior. A new elevator if required would need to be located on the outside of the building with elevator and associated enclosure would incur very significant expense.

9. Provide documented cost estimates for each portion of the waiver request and identify any additional supporting data which may affect the cost estimates. For example, for vertical accessibility, the lowest documented cost of an elevator, ramp, lift or other method of providing vertical accessibility should be provided, documented by quotations or bids from at least two vendors or contractors.

a. \_Estimated Cost for new Elevator per Email from Otis Elevator (Kyle R. Stopa- Senior Account Manager) dated 9-19-13\_\_\_\_\_\_

b. Estimated Cost for new Elevator per Email from Schindler Elevator (Christopher Curtis-Senior Account Manager) dated 9-23-13

c. Budget Cost Estimate dated 9-27-13 as prepared by Mallen Construction for full alteration along with separate costs/breakdown for new elevator option & ADA Accessibility Renovation Costs.

10. Licensed Design Professional: Where a licensed design has designed the project, his or her comments MUST be included and certified by signature and affixing of his or her professional seal. The comments must include the reason(s) why the waiver is necessary.

Architect respectfully submits several reasons for needing approval for the vertical accessibility waiver. Overall costs for this full alteration of both the interior and exterior are very significant for the existing building which is currently un-occupied and in need of significant repairs. Current design provides for full accessibility from the new parking lot areas into the renovated 1<sup>st</sup> floor areas which are also fully accessible to the Public and Employees. The added costs of providing a new elevator and enclosure would significantly increase the construction cost and render the project unfeasible. The attached costs for the elevator attempt to demonstrate that the addition of the elevator would exceed 20% of the alteration costs and be Disproportionate per FAC 202.4.1. Attached estimates also attempt to show estimated costs being spent on alterations and affording accessibility to the building's primary function areas.

Overall, Owner is trying to fully renovate the building/site, provide for full accessibility to the 1<sup>st</sup>

FBC 2012-01 Request for Waiver

floor, yet keep the overall construction costs affordable as the Owner currently has one Tenant committed to lease both floors. Architect has met with City of Jacksonville Building Officials on several occasions to review and discuss the project to try to ensure that we are on the same page with the Building & Accessibility Code, yet trying to keep the project feasible.

Respectfully Submitted,

Л Signature

Christopher P. Noel, AIA, LEED AP\_\_\_\_\_ Printed Name

Phone number 904-798-8333\_

(SEAL)

10-03-13

FBC 2012-01 Request for Waiver

#### **CERTIFICATION OF APPLICANT:**

I hereby declare that the applicable documents in support of this Request for Waiver are attached for review by the Florida Building Commission and that all statements made in this application are to the best of my knowledge true and correct.

Dated this 3pb day of UCNBER, 2013.

Signature Christopher P. Noel, AIA, LEED AP

Printed Name

I understand that if I falsify, misrepresent, or omit any material information on this document, the Commission may revoke any order and will notify the building official of the permitting jurisdiction.

KNOWINGLY MAKING A FALSE STATEMENT IN WRITING WITH THE INTENT TO MISLEAD A PUBLIC SERVANT IN THE PERFORMANCE OF HIS OFFICIAL DUTY IS A MISDEAMEANOR OF THE SECOND DEGREE PURSUANT TO SECTION 837.06 F.S. AND SECTION 775.083, F.S.

FBC 2012-01 Request for Waiver

## 2501 Riverside Ave. Jacksonville FL.

#### **REVIEW AND RECOMMENDATION BY LOCAL BUILDING DEPARTMENT.**

Please state why the issue is being referred to the Florida Building Commission as well as a recommendation for disposition. The Building Official or his or her designee should review the application and indicate that to the best of his or her knowledge, all information stipulated herein is true and accurate. Further, if this project is complete, explain why it is being referred to the Commission. The Building Official or his or her designee should sign a copy of the plans accompanying this application as certification that such plans are the same as those submitted for building department review. Please reference the applicable section of the Accessibility Code.

### a. PER 202.4.1 IN FL. HORESSIBILITY CODE, 2010 EDITION

b.\_\_\_\_\_ с.

Has there been any permitted construction activity on this building during the past three years? If so, what was the cost of construction?

[] Yes No Cost of Construction
Comments/Recommendation WE HAVE REVIEWBD THE SUBMITTIEL
PACEAGE & AGRIGE W/ WAIVER REQUEST
Jurisdiction DWAL COUNTY (CITY OF JACKSCHNIUE)
Building Official or Designee Chill C Carlos
Christian Enic Parder
Printed Name
BUI399 Certification Number
904-255-850F Telephone/FAX
Pardeeecoj.net Email Address
Address: 214 North Hogan St. Jacksonville A 32202

FBC 2012-01 Request for Waiver

Rule 61G20-4.001 effective 4/25/2013

2501 Riverside Avenue Renovation- This sheet Not Applicable.

Certification of Licensed Design Professional for Replicated Designs to be Placed on Consent Agenda

Note: Fill out pages \_\_\_\_\_\_ only for cases in which design documents are duplicates of previously approved waivers and the project can be placed on a Consent Agenda.

I,\_\_\_\_\_, a licensed architect/engineer in the state of Florida, whose Florida license number is \_\_\_\_\_\_, hereby state as follows:

2. I hereby certify that to the best of my knowledge and belief to the Florida Building Commission that the design documents for the (insert project described in paragraph 1 above) \_\_\_\_\_\_ are the same as the design documents previously submitted to the Commission and referenced in paragraph 3 below, except that the two projects are built or to be built on different parcels of land at different locations.

3. The licensed design professional of record (identify the licensed design professional of record), \_\_\_\_\_\_\_, prepared the design documents for the project known as

for which the majority of the Accessibility Advisory Council recommended approval and the Commission granted a waiver of one or more accessibility requirements in Final Order No.

Printed Name: \_\_\_\_\_\_ Affix certification seal below:

Address: \_\_\_\_\_

Telephone: \_\_\_\_\_\_

E-Mail Address: \_\_\_\_\_

FBC 2012-01 Request for Waiver 2501 Riverside Avenue Renovation- Existing Exterior Photos Request for Vertical Accessibility Waiver



DSCN4733.jpg

TTV Architects, Inc.

### 2501 Riverside Avenue Renovation- Existing Interior Photos Request for Vertical Accessibility Waiver



20130521\_151044.jpg



20130521\_151248.jpg



20130521\_151236.jpg



20130521\_155022.jpg

TTV Architects, Inc.

Ack	erman F	Riversid	le A	lve			
<u>09.17.13</u>							
							3,762
	Estimated Quantity	Unit		Unit Cost		Total	Cost / SF
1000 GENERAL REQUIREMNTS				· · · · · · · · · · · · · · · · · · ·			· · · · · · · · · · · ·
GENERAL INDIRECT COST INCL SUPERVISION	20	wк	\$	1,500.00	\$	30,000.00	7.97
PERMIT	1	LS	\$	1,500.00	\$	1,500.00	0.40
FINAL CLEAN	3,762	SF	\$	0.35	\$	1,316.70	0.35
Dumpsters	4	EA	\$	300.00	\$	1,200.00	0.32
Lead Mold Allowance	1	LS	\$	10,000.00	\$	10,000.00	2.66
Rotten Wood Allowance	1	LS	\$	10,000.00	\$	10,000.00	2.66
2000 SITE CONSTRUCTION					\$		0.00
SITEWORK	1	LS	\$	80,000.00	\$	80,000.00	21.27
TREE PROTECTION	INCL						
EARTH WORK	MINIMAL						
STORM DRAINAGE	NA						· · · ·
CURB AND GUTTER	NA						
ASPHALT PAVING	INCL						
PAVEMENT MARKING	INCL						
CONCRETE PAVING	NA						
Parking Lot Stripping	INCL						17 din din 2 din 2
Site Sidewalks and Ramp	1	LS	\$	15,600.00	\$	15,600.00	4.15
Landscape & Irrigation Allowance	1	LS	\$	20,000.00	\$	20,000.00	5.32
		A			\$	-	0.00
Aluminum Fencing	418	LF	\$	61.00	\$	25,498.00	6.78
Dumpster Fence & Gates	1	LS	\$	1,000.00	\$	1,000.00	0.27
EXTERIOR GAS	NA						
Water tap for fire sprinkler	IN FIRE SPRINKLER						
EXTERIOR FIRE MAIN & Backflow	IN FIRE SPRINKLER						
EXTERIOR WATER	NA						
EXTERIOR SEWER	NA						
INTERIOR BUILDING DEMO	3,762	SF	\$	3.75	\$	14,107.50	3.75
Crawl space not accessible don't know if piers are	_	15	<u></u>		\$	_	0.00
Mold 222	_	LJ			\$	-	0.00
	I				Ψ		0.00

	Estimated						
	Quantity	Unit		Unit Cost		Total	Cost / SF
3000 CONCRETE					\$		0.00
SEE SITE AND STAIRS	_				\$	-	0.00
					\$	-	0.00
5000 METALS					\$	u.	0.00
STEEL STAIR	1	EA	\$	8,000.00	\$	8,000.00	2.13
STAIR ENGINEERING	1	EA	\$	1,000.00	\$	1,000.00	0.27
SS RAILINGS	90	LF	\$	303.00	\$	27,270.00	7.25
WOOD TREAD & RISER	32	EA	\$	65.00	\$	2,080.00	0.55
Steel Beam / INCL FOUNDATION	1	LS	\$	5,500.00	\$	5,500.00	1.46
					\$	-	0.00
		1.0	_	F 000 00	<u>۴</u>	5 000 00	4.00
		LS		5,000.00	\$	5,000.00	1.33
	1	LS	- 15	15,200.00	\$	15,200.00	4.04
			<b>_</b>		\$	-	0.00
Breakroom	10		\$	300.00	\$	3,000.00	0.80
Open Offices/ workstations	30		\$	300.00	\$	9,000.00	2.39
7000 THERMAL & MOISTURE PROTECTION							
BATT INSULATION	4,900	SF	\$	1.00	\$	4,900.00	1.30
ROOFING	NA						
SOFFIT	NA						
FASCIA	NA		1-				MANALOS 6
GUTER & DWN SPOUT	NA		+				
JOINT SEALANTS	NA		+				
Sky Lights	NA						
8000 DOORS AND FRAMES							
ENTRY DOORS	INCL						
WOOD DOORS	17	EA	\$	1,250.00	\$	21,250.00	5.65
FINISH HDW	17	EA	\$	500.00	\$	8,500.00	2.26
ACCESS DOORS					\$	· _	0.00
					\$	-	0.00
ALUMINUM WINDOWS					\$	-	0.00
GLAZING					\$	-	0.00
GLASS WALL	12	LF	\$	300.00	\$	3,600.00	0.96
Windows					\$	-	0.00
FEATURE WALL 5 X 9	1	EA	\$	10,000.00	\$	10,000.00	2.66
							0.00
					\$	-	0.00
9000 FINISHES			<u> </u>				
METAL STUDS	6,614	SF	\$	1.25	\$	8,267.50	2.20
DRYWALL	8,646	SF	\$	1.25	\$	10,807.50	2.87
WOOD FLOOR REFINISH	280	SF	\$	4.00	\$	1,120.00	0.30
HARD TILE	321	SF	\$	15.00	\$	4,815.00	1.28
VCT	NA						

	Estimated					
	Quantity	Unit	Unit Cost		Total	Cost / SF
CARPET	310	SY	\$ 25.00	\$	7,761.11	2.06
PAINTING	1	LS	\$ 15,500.00	\$	15,500.00	4.12
				\$	-	0.00
10000 SPECIALTIES				\$	-	0.00
SIGNAGE				\$	-	0.00
PANEL SIGNS	1	LS	\$ 700.00	\$	700.00	0.19
PLAQUES	NA					
LETTERS	NA					
FIRE EXTINGUISHERS	3	EA	\$ 200.00	\$	600.00	0.16
TOILET ACCESS	1	LS	\$ 650.00	\$	650.00	0.17
FRONT DOOR AWNING	1	LS	\$ 2,000.00	\$	2,000.00	0.53
APPLIANCES	NA					
BLINDS	NA					
				\$	. –	0.00
13000 Elevator		EA	\$ -	\$	-	0.00
15000 MECHANICAL						
Fire Sprinkler	1	LS	\$ 57,800.00	\$	57,800.00	15.36
HVAC	10	tons	\$ 2,000.00	\$	20,000.00	5.32
Plumbing	5	FIX	\$ 2,000.00	\$	10,000.00	2.66
16000 ELECTRICAL	1	LS	\$ 20,000.00	\$	20,000.00	5.32
Electrical Light Fixture - Allowance	1	LS	\$ 8,000.00	\$	8,000.00	2.13
Site Electrical	1	LS	\$ 10,000.00	\$	10,000.00	2.66
				\$	512,543,31	136.24
Contractors fee			 12%	\$	61,505,20	16 25
Estimated Architectural Fee's				\$	-	0.00
ΤΟΤΑΙ	·····		 	\$	574.048.51	152 59
			 	*	0,0 .0.01	152.55

9/17/13 Gent to Arch.

#### <u>Ackerman Riverside Ave</u> <u>BUDGET</u> <u>ASSUMPTIONS AND CLARIFICATIONS</u> <u>09.17.13</u>

#### GENERAL

- 1. Builder's risk insurance will be provided by Mallen.
- 2. Contractors General Liability and Workers Compensation insurance are included.
- 3. Building Permit fees are included.
- 4. Temporary toilet facilities will be provided by Mallen.
- 5. Foundation surveys and as-built surveys are excluded.
- 6. Temporary power and water will be provided by the owner.
- 7. Permit plans and engineering are to be provided by owner.
- 8. Meter deposits and initial service connection fees for water and electric utilities are to be provided and paid for by the owner.
- 9. The irrigation water meter is by owner.
- 10. Payment & Performance bond is excluded for all trades.
- 11. Price is based on performing job in one phase from start to finish.

#### SITE – Division 2

- 1. All sanitary sewer and domestic water impact connection and meter fees are excluded.
- 2. Stop signs, handicapped signs, and street signs are included.
- 3. Monument sign Allowance \$2,000
- 4. Owner to provide initial field control survey points.
- 5. All tree mitigation is excluded.
- 6. Underground sleeving is included for irrigation system only; all other sleeving is in landscape allowance
- 7. Drive & Parking is to be 4" concrete paving.
- 8. Downspouts no work included
- 9. 4 foot aluminum fence at parking area
- 10. Concrete curbing is not included.
- 11. Landscape and irrigation is included. Allowance \$20,000
- 12. No work included for JEA poles etc.

#### Ackerman Riverside Ave <u>BUDGET</u> ASSUMPTIONS AND CLARIFICATIONS

- 13. Picnic tables, trashcans, playground equipment or any other site amenities are to be provided and installed by owner.
- 14. Subsurface exploration It is assumed that all soils on site are adequate for the construction methods and no bad soils will have to be removed.
- 15. Clearing Price to clear and haul off site is included.
- 16. Demolition demo existing drives and parking areas and interior of building
- 17. Site Drainage NA
- 18. Site Utilities NA
- 19. Site Lighting Allowance
- 20. Dumpster fence & gates
- 21. No gas main is included

#### STRUCTURAL – Division 3 - Concrete

- 1. Pad foundations below the steel columns are included. 3 each
- 2. Side walks are included.

#### STRUCTURAL – Division 4 - Masonry

1. No masonry work

#### STRUCTURAL - Division 5 - Metals

- 1. Structural steel columns and beam at first floor.
- 2. Structural steel stairs stringer. Wood treads & risers
- 3. Stainless steel handrails and railing at stair.

#### ARCHITECTURAL – Division 6 – Wood & Plastic

- 1. Wood window sill and apron are included at all interior and exterior windows.
- 2. Wood base is included.
- 3. Wood jambs and head trim are included at all interior and exterior doors.
- 4. All cabinets note locations breakroom and open office/ workstations
- 5. Painted wood base.
- 6. Feature wall Lumicore 5 x 16 Allowance
- 7. Built in work to be P lam with solid surface tops

#### <u>Ackerman Riverside Ave</u> <u>BUDGET</u> ASSUMPTIONS AND CLARIFICATIONS

8. Stairs to be wood treads and risers with steel stringer system and stainless steel railing system similar to HDI Circum

#### ARCHITECTURAL -- Division 7 -- Thermal & Moisture Protection

- 1. Gutters and downspouts NA
- 2. All exterior walls are to receive batt insulation.
- 3. Interior walls around restroom are batt insulation.
- 4.  $2^{nd}$  floor ceilings are to be R-30 batt insulation.
- 5. Skylights NA
- 6. No spray fire proofing is included.

#### ARCHITECTURAL – Division 8 – Doors and Windows

- 1. Office doors are to be stained wood with full glass
- 2. Closet doors are to be stained wood no glass
- 3. Door in Glass wall to be stained wood with full glass
- 4. New rear door is to be wood
- 5. New Front door is to be wood
- 6. All finish hardware is to be commercial grade as selected by the contractor.
- 7. Keying for the hardware is included.
- 8. Wood base.
- 9. Wood Window stools.
- 10. Wood Window apron.
- 11. No crown molding.
- 12. No chair molding.

#### ARCHITECTURAL - Division 9 - Finishes

- 1. Stucco NA
- 2. Exterior tile NA
- 3. Interior walls are to be 3 5/8" metal stud.
- 4. Exterior walls are to be 1 5/8" metal stud.

#### Ackerman Riverside Ave <u>BUDGET</u> ASSUMPTIONS AND CLARIFICATIONS

- 5. Drywall ceiling are to be 5/8" 2<sup>nd</sup> floor only. First floor is exposed wood joist
- 6. Walls are to be  $\frac{1}{2}$ " with a level four finish.
- 7.  $2^{nd}$  floor ceiling is to have  $\frac{1}{2}$ " floating channel
- 8. Carpet is per the finish schedule.
- 9. Gypsum board walls are to receive 1 coat primer, 2 coats latex eggshell. Gypsum board ceilings are to receive 2 coats flat latex.
- 10. Wood doors, window sills and baseboards are to receive 1 coat primer, 2 coats alkyd semi-gloss.
- 11. Paint exterior soffit facia and windows.
- 12. No specialty painting is included.

#### ARCHITECTURAL – Division 10 - Specialties

- 1. Toilet Accessories are included.
- 2. Four fire extinguishers and cabinets are included.
- 3. Appliances NA
- 4. Window blinds NA
- 5. Restroom grab bars are included.
- 6. Awnings at front door.

#### EQUIPMENT – Division 11

1. NA.

#### FURNISHINGS – Division 12

1. NA

SPECIAL CONSTRUCTION – Division 13

1. NA

**CONVEYING SYSTEMS – Division 14** 

1. N/A

#### Ackerman Riverside Ave <u>BUDGET</u> ASSUMPTIONS AND CLARIFICATIONS

MECHANICAL – Division 15 - HVAC

#### 1. HVAC 10 tons

MECHANICAL – Division 15 - Plumbing

2. Two restrooms

ELECTRICAL – Division 16

- 1. A/C wiring
- 2. 59 receptacles
- 3. 27 switches
- 4. 18 Data/Phone cat5e
- 5. Wiring for lighting
- 6. Fire alarm monitor panel
- 7. Electrical site work Allowance
- 8. No electrical service. Use existing
- 9. All wiring in MC cable
- 10. The security system is to be by owner.
- 11. No landscaping lighting is included.
- 12. No generator systems are included.
- 13. Light fixture allowance \$8,000

### Mallen Construction Inc.

10702 Hood Road South Suite #8 Jacksonville FL 32257-3244 904-880-5580 904-880-8761 FAX

website: www.mallenconstruction.com

DATE: 9/26/13

RE: Ackerman Riverside

My empile keep getting bounced back. Here are the two items we discussed, Contact me with questions Vellision

PHONE NO:

TO	FROM:
NAME: Chris Noel	NAME: Allen Davis
COMPANY: TTU Arch.	Number of pages including cover
FAX #: 798-8335	<u> </u>

		1					
						(pdi	
Acke	erman F	liversic	le A	ve	l	Mol	
09.26.13						200	
			_				
	Estimated			I luib Cook		Total	Contr
ADA Elements	Quantity	Unit	_			TUtal	Cost / SF
New ADA parting space sidewalk & signage		10		1 450 00	\$	1,450,00	- 1994 - 1994 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997
New ADA parking space, sidewalk & signage						.,	
New ADA ramp & handrails	144	SF	\$	40.00	\$	5,760.00	1914 - Marine Conference
						100 yr 10 kennedd ar	
Enlarge existing exterior opening, New accessable							
door & hardware	1	EA	\$	3,800.00	\$	3,800.00	
						* (FL74)Filmlan and an anone us warmen and to the	an a
New accesible break room & millwork	78	SF	\$	152.00	\$	11,856.00	
	100	or	- e	152.00	¢	16 416 00	
New ADA restrooms	108	121		132.00	φ	10,410.00	
New accessible conference room	188	SE.	\$	152.00	S	28,576,00	
			-		<u> </u>		
New ADA compliant doors & hardware	14	EA	\$	1,650.00	\$	23,100.00	The development and a second statement
							antan 2 dif () (b) daif (b) all bounds in an iteration and an anna an
New accessible work area millwork	186	SF	\$	152.00	\$	28,272.00	
New Fire alarm system with accessible audible/							
Visible Alarms	1	LS	\$	5,200.00	\$	5,200.00	
·	- <b>1</b>						
SUBTOTAL					\$	124,430,00	STATEST AT SMALL A COLORADO AND A COLORAD
Contractors fee					INCL		a ya nya ya mana kata kata kata kata nya ya kata kata kata kata kata kata kata
Estimated Architectural Fee's			1		\$	-	and a subsequences and address and an excerne
TOTAL	an a		-		1		
		A					

•••

	والمربوب والمستعم والمعالية والمتالية											
		<u> </u>										
Ackerman Riverside Ave												
09.27.13												
	Estimated											
Elevator Shaft	Quantity	Unit		Unit Cost		Total	Cost / SF					
Site work	1	LS	\$	500.00	\$	500.00						
Elevator Plt	1	EA	\$	5,200.00	\$	5,200.00						
Machine Room	-	SF	\$	50.00	\$							
Elevator Lobby	144	SF	\$	150.00	\$	21,600.00						
Elevator Shaft 2 stories Stucco finish on CMU	144	SF	\$	140.00	\$	20,160.00						
Modify Existing Building	1	کا	\$	3,000.00	\$	3,000.00						
Electrical	1	LS	\$	5,000.00	\$	5,000.00						
Elevator	1	EA	\$	46,000.00	\$	46,000.00						
							<b># #1</b> 00000000000000000000000000000000000					
SUBTOTAL		<u></u>			\$	101,460.00						
Contractors fee				12%	\$	12,175.20						
Estimated Architectural Fee's					\$	-						
TOTAL					\$	113,635.20						

Emailed glunli3

#### **Chris Noel**

From: Sent: To: Subject: Stopa, Kyle R <Kyle.Stopa@otis.com> Thursday, September 19, 2013 4:18 PM Chris Noel Otis Hydrofit

Chris, Otis Hydrofit hydraulic elevator 2 stops, front openings only, about 12' rise, standard finishes, you're looking at about \$50K. This doesn't include shaft, routing power, etc., the standard non-elevator items. Please let me know if you have any questions on this info.

Sincerely, *Kyle R. Stopa* | Sr. Account Manager

**Otis Elevator Company** | 6631 Executive Park Court N. #206, Jacksonville, FL 32216 ☎(904)296.6847 ext 16 | € Cell (904)219-6856 | 昌Fax (904)296-9483. <u>kyle.stopa@otis.com</u>



Subject: Attachments: FW: Commercial 2 Stop Elevator Costs 201309201246.pdf; Final (low-res) 3300 Capabilities Brochure.pdf; 3300 LD Sheet.pdf

From: chris.cornelius@us.schindler.com [mailto:chris.cornelius@us.schindler.com] Sent: Monday, September 23, 2013 8:58 AM To: Chris Noel Subject: Re: Commercial 2 Stop Elevator Costs

Chris,

Attached please find a hatch drawings and specification summary for a basic two stop hydraulic. A good current budget price would be \$43,000. Also, please be advised, we have a newer product that is a machine room less traction elevator that we could provide at a budget price of \$46,000. Using this product, there would be some cost savings ie... building a machine room, along with providing AC in the machine room, also the motor horsepower is typically under 10 hp. therefore, that would also be a savings to the owner. I have attached a couple brochures showing details of this product.

After you have had a chance to review, if you should have any questions, please do not hesitate to call.

Regards,

Chris

Chris Cornelius | District Sales Specialist Phone 904.880.4922 ext. 223 | Mobile 904.237.3805 | Fax 904.880.4916 chris.cornelius@us.schindler.com

Schindler Elevator Corporation | Jacksonville 9143 Philips Hwy. Suite #260 | Jacksonville, Florida 32256, USA www.us.schindler.com

#### Please consider your environment.

Schindler supports sustainable urban development with safe, reliable and ecologically sound mobility solutions.

#### <u>Schindler Elevator Corporation</u> Hydraulic Elevator Specification Summary

4

	Project Informat Opportunity ID: Unit(s) In EstIma Units in Bank: Product Code: Sales Office: Installation Offic	ite: 01 01 113 6431 ee: 6431	Sales Rep Information: Chris Cornelius 9143 Philips Highway Suite 260 Jacksonville, FL 32256 Phone: (904) 880-4922 Ext 223 Fax: (904) 880-4916 Chris.Cornelius@us.schindler.com
Product: Application: Platform Type: Capacity: Speed: Travel: Future Travel: Stops: Doors: Power Supply:	Schindler 330A (TM) 330A Holeless Single Jack General Purpose 2100 Lbs 100 FPM 11 Ft. 8.000 In. None 2 (2 Front / 0 Rear) Single Speed Side Opening 208 Volts 60 Hz 3 Phase	Opening Size: Cab Height: Cab Type: Pit Depth: Overhead: Platform Width: Platform Depth: Hatch Width: Hatch Depth: Seismic Equipment:	3 Ft. 0.00 In. X 7 Ft. 0.00 In. 8 Ft. 0 In. 125-Cab with Hung Panels 4 Ft. 0.000 In. 12 Ft. 0.000 In. 6 Ft. 0 1/4 In. 5 Ft. 4 In. 7 Ft. 4.000 In. 6 Ft. 0.000 In. N
Cab: Cab Panels: Cab LH Wall: Cab RH Wall: Cab Rear Wall: Cab Base: Base, Frieze, Reveal: Front Return, Transom: Cab Doors: Canopy: Ceiling: Cab Threshhold: Handrail Type: Handrail Finish: Handrail Finish: Handrail Location: Handrail Row Qty: Platform Recess: Protective Pads: Protective Pads Source: Cab Finished Floor:	Plastic Laminate M999 Baked Enamel E999 Baked Enamel E999 Baked Enamel E999 None Wone #4 Stainless Steel #4 Stainless Steel Gettysburg SC02 Removable Flat Aluminum Flat (1/2" x 2") Aluminum Rear 1 0.375 None None Carpet By Others	Features: Follow IBC - 2006 Audible Gong (Std) Low Oil Bypass (Std) Infrared Door Protection (Std) Phase Monitor Relay (Std) Independent Service/HES (Std) Soft Start Adjacent Machine Room Shutoff Valve Qty: 2 Muffler QKS16 Door Operator 9 Pound Rails Keyed Emergency Stop Switch Top Exit Switch ADA Compliant Phone Silding Guide Shoes 1 Speed Fan Firefighter's Service Phase 2 Class B Fire Rating For Cab	Entrances: Emergency Escutcheons Doors: (2) Baked Enamel E999 Frames: (2) Baked Enamel E999 Sills: (2) Aluminum Sill Mounting: (2) Easy Match Hall Fixtures:
Cab Fixtures:     Type:   HT     Finish:   Black Lex     (1) LED. Car Position Indic:	an with #4 Stainless Steel	Pressure Switch Hush Kit Pit Ladder Source: GC	HT-Jamb Mounted Hall Fixtures Finish: (2) Lexan Push Buttons (1) Separate FER Switch

#### New Product Service:

Locking Service Panel (1) Car Lantern(s) Certificate Frame

1 Main COP

#### 12 Months, 8 Hours Callback

This bid is subject to change after forty-five (45) days.

06/27/13 11:47PM

(Please see Schindler shop drawings for exact rough masonry opening position)





32 la\_l.rpt

# Schindler 3300 MRL Traction Elevator General Purpose

Standard Speeds: 100, 150 fpm (0.5, 0.75 m/s) Openings: 8 Front Travel: Up to 98'-5" (30.0 m)



# Schindler 3300 MRL Traction Elevator General Purpose

Standard Speeds: 100, 150 fpm (0.5, 0.75 m/s) Openings: 8 Front Travel: Up to 98'-5" (30.0 m)

#### Section and plan view



Front entrance only, two-speed side opening (2SSO)



Front entrance only, single-speed center opening (SSCO)





#### Machine room-less traction elevator with frequency-controlled drive

Capacity 2100 - 3500 lbs, 14 - 23 passengers

Capacity	Passengers max.	Speed	Number of stops max.	Available entrances max.		Car Do						Sh	aft		Travel height max.					
								Door type												
lbs (kg)		fpm (m/s)			A in (mm)	B in (mm)	C in (mm)		D in (mm)	E in (mm)	F (iii) ft (mm)	G ft (mm)	H ft (mm)	l (iv) ft (mm)	J <sub>(vi)</sub> ft (m) / FPM (m/s)					
2100 (950)	14	100/150 (.5/.75)	8	Front only	5'-9 <sup>3</sup> /8" (1761)	4'-4 <sup>7</sup> /8" (1343)	7'-9" (2366)	2550	3′ (915)	7′ (2134)	7'-4" (2235)	5'-9" (1755)	5'-0" (1524)	12'-7" (3835)	59' (17.7) / 100 (.5) 98'-5" (30.0) / 150 (.75)					
2500		100/150			6'-9 <sup>-3</sup> /8"	6'-9 <sup>3</sup> /8"	6'-9 <sup>3</sup> /8"	6'-9 <sup>3</sup> /8"	3/8" <u>1'-1 7/8</u> " 7'-9"		-9 <sup>3</sup> /8″ 4′-4 <sup>7</sup> /8″	7'-9″	2550	3'-6" (1067)	7′ (2134)	8'-4" (2540)	5'-9" (1755)	5'-0" (1524)	12'-7" (3835)	59' (17.7) / 100 (.5)
(1135)	17	(.5/.75)	8	Front only	(2066)	(1343) (2366)	(2366)	SSCO	3'-6" (1067)	7′ (2134)	8'-4" (2540)	5'-9" (1755)	5'-0" (1524)	12'-7" (3835)	98'-5" (30.0) / 150 (.75)					
3000		100/150	_	_	6'-9 <sup>3</sup> /8″ 4'-10 <sup>7</sup> (2066) (1495			6'-9 <sup>3</sup> /8" 4'-10 <sup>7</sup> /8" 7'-9 (2066) (1495) (236	-10 <sup>7</sup> /8″ 7′-9″	2550	3'-6" (1067)	7′ (2134)	8'-4" (2540)	6'-3" (1905)	5'-0" (1524)	12'-7" (3835)	59' (17.7) / 100 (.5)			
(1360)	20	(.5/.75)	8	Front only		(2066)	56) (1495)		(2366)	(1495) (2366)	95) (2366)	SSCO	3'-6" (1067)	7′ (2134)	8'-4" (2540)	6'-3" (1905)	5'-0" (1524)	12'-7" (3835)	98'-5" (30.0) / 150 (.75)	
3500	22	100/150	0	<b>F 1 1</b>	6'-9 <sup>3</sup> /8"	5'-6 <sup>7</sup> /8″	7'-9″	2550	3'-6" (1067)	7′ (2134)	8'-4" (2540)	6'-11" (2110)	5'-0" (1524)	12'-7" (3835)	59' (17.7) / 100 (.5)					
(1590)	23	(.5/.75)	8	Front only	(2066)	) (1699) (2366)		SSCO	3'-6" (1067)	7′ (2134)	8'-4" (2540)	6'-11" (2110)	5'-0" (1524)	12'-7" (3835)	98'-5" (30.0) / 150 (.75)					
					A Insi B Insi C Insi	ide cab width ide cab depth ide cab heigh	n n nt	2SSO 2 SSCO S	2-speed side opening () ingle speed opening	center	F Sh G Sh H Pit I Ov	aft width aft depth depth erhead								
Notes:								<b>E</b> [	Door Height											

(i) 2SSO doors available with right or left opening.

(ii) Duplex operation available.

(iii) For areas in seismic zone 2 or greater, provide additional 2" (50 mm) on the F dimension.

(iv) Clear overhead is defined as the lowest point below any obstruction such as: hoist beam(s), building beams, or roof structure.
(v) Where permitted by code, no control closet is required. A 3-phase and 110v disconnect must be located in both the hoistway overhead and a location in the building outside of the

hoistway. This is not required to be an elevator-dedicated space. (vi) Travel height max. varies depending on speed (FPM) and capacity (lbs).

# Schindler 3300 MRL Traction Elevator General Purpose

Standard Speeds: 100, 150 fpm (0.5, 0.75 m/s) **Openings: 8 Front** Travel: Up to 98'-5" (30.0 m)

#### General requirements

Requirements for installation vary by type of equipment selected. These general requirements assist you in preparing your building for the installation of Schindler elevators. All designs, clearances, construction, workmanship and materials, unless specifically excepted, shall be in accordance with the requirements of the latest published ASME A17.1 Code for electric traction elevators plus applicable building code and local codes. State or local requirements must be used if more stringent

Items to be provided — A complete installation includes the following items not included in the elevator contract:

- Clear, plumb hoistway, with variations on a minimum dimension hoistway not to exceed  $-0^{\circ}$ 1. and +1" (25.4 mm) per side at any point. Tolerance may increase to variations not to exceed -1" (-25.4 mm) and +1" (25.4 mm) per side at any point when an additional 2" (50.8 mm) is provided on the hoistway width dimension.
- Two-hour fire resistance of hoistway walls or rating to meet applicable local codes. 75° bevel 2 guards on all projections, recesses or setbacks over 4" (102 mm) except on side used for loading or unloading. The overhead machinery space temperature at top of hoistway to be maintained between 32° F (0° C) and 110° F (43° C) and < 95% relative humidity, non-condensing.
- 3. Supports for rail brackets at pit, each floor and one or two locations above top floor in the overhead (application dependent). Divider beams between hoistways at each floor level and one or two locations above top floor in the overhead for quide rail bracket supports. Locate per layout. For masonry block hoistway construction, Schindler will provide rail bracket inserts for installation by others, located per the Schindler final layout drawings. Where inserts are not used, hollow masonry blocks are not acceptable for bracket fastening. Provide 125 mm (5") concrete belt around hoistway or other acceptable support at each floor, in overhead, and intermediate levels (if required). For max. rail bracket vertical spacing, contact your local sales representative.
- Supply hoist/safety beam for elevator construction and service work. Beam to run across the width 4 of the elevator shaft. Locate per layout. Hoist beam to be left in place after elevator installation.
- A temporary work platform is required for installation. It is to be constructed at the top floor of each elevator. It must comply with applicable governing codes and regulations. The platform shall be securely fastened to the building structure. Erection, maintenance, and removal are by others. (Reference Schindler drawing TD440.)
- Lighting, light switch and duplex receptacle (GFCI) for each elevator, in the center of hoistway pit and in the elevator overhead/machinery space, as indicated by Schindler. The pit light switch located adjacent to access door.
- Recesses, supports, and patching, as required, to accommodate hall button boxes, signal fixtures, etc. (if required).
- All barricades outside elevator hoistways or between elevators inside hoistways.
- Dry pit reinforced to sustain normal vertical forces from rails and buffers.
- 10. Drains & sumps in elevator pits, where provided, shall comply with the plumbing code, and shall be provided with a positive means to prevent water, gases and odors from entering the hoistway. The cover must be secured and level with the pit floor and located to clear elevator equipment. (Cannot be connected directly to storm drain or sewer.)
- 11. Pit ladders shall be provided where required.

#### Inspection and test panel

- 12. A switch placed adjacent to the jamb-mounted inspection and test panel enclosure shall control lighting in front of the panel. Minimum lighting to be 200 lux (19 fc).
- A lockable, 13 1/2" x 15 1/2" x 3 1/2" metal cabinet with group-1 key provided by Schindler to 13. house the required electrical schematics and maintenance history documents, shall be wallmounted, adjacent to the disconnect switch, by others, preferably at the top landing.
- 14. Provide, preferably on the same floor as the elevator inspection and test panel, a lockable panel with a fused disconnect switch or circuit breaker suitable for 3-phase power for the elevator control, and a fused disconnect switch or circuit breaker for car lighting for each elevator in a separate lockable panel adjacent to the 3-phase panel or within the 3 phase panel. The panel(s) must be accessible to qualified personnel only (NEC NFPA req. 620.51[C]) with a Group 2 key (ASME A17.1 req. 8.1.3). Alternative locations for the panel(s) can be considered, provided they are located in accessible areas without obstructions to qualified personnel in compliance with NEC NFPA req. 620.51(C). Locate and mark the panels and disconnects with appropriate signage, (NEC NFPA 70 req. 620-22 and 620-51, or CSA C22.1-02 sections 38-022 and 38-053). The disconnects or circuit breakers may also be located without panels in a Group 2 key-secured

U.S. Headquarters. Morristown, New Jersey Tel. 973.397.6500

#### www.us.schindler.com

Canada Headquarters. Scarborough, Ontario Tel. 416.332.8280

www.ca.schindler.com

room identified and dedicated to elevator apparatus only, and in all cases must be capable of being locked in the open position with a lock that cannot be removed from the devices or panel(s). FOR DRIVE IN HOISTWAY CONFIGURATION ONLY: Electrical contractor to supply an additional lockable auxiliary non-fused disconnect in the hoistway at the location of the drive (motor controller), along with wiring from the main disconnect to the auxiliary disconnect (see also NEC NFPA 70 - 2008 reg. 620.51[C]{1}). This disconnect must also be lockable in the open position with a secured lock that cannot be removed from the device.

#### Control spaces (When specified in lieu of an Inspection and Test Panel, a partial or full body entry space/room shall be provided.)

- 15. Enclosed and protected control space at top landing adjacent to the hoistway wall closest to the elevator hoist machine. Two-hour fire rating of control space walls or rating to meet applicable local codes
- 16. Provide fire-rated, self-closing, self-locking door. Door must be capable of opening 180 degrees for access to control space
- 17. 42" (1067 mm) minimum clear space is required in hallway in front of control space door and top hoistway entrance for service barriers. Additional hallway width may be required, subject to local building, fire and ADA codes.
- 18. The temperature in front of the control space must be maintained between 32° F (0° C) and 104° F (40° C) and less than 95% relative humidity, non-condensing, for proper operation of equipment.
- 19. Disconnects for each elevator must be provided per National Electrical Code (NFPA No. 70) and located inside the elevator control space.

#### Other wiring

- 20. Suitable copper feeder, ground and branch wiring circuits for signal system and power operated door. Feeder and branch wiring circuits for car light and fan.
- 21. Telephone outlet provided at the inspection and test panel or in control closet (where applicable).
- 22. All conduit and wire runs remote from either the control space or hoistways (if required)
- 23. Heat, smoke or products of combustion-sensing devices connected to elevator control space terminals when such devices are required.

#### **Emergency provisions**

- 24. Elevator Firefighter's and other emergency services, depending on height of the building or number of landings, per ASME A17.1 Rule 2.27.3 and local codes.
- 25. Elevator Firefighter's and other emergency services' wiring and interconnections to automatic sprinkler systems or heat and smoke-sensing devices furnished by others.
- 26. When emergency/standby power operation of elevators is required, the Electrical Contractor should coordinate with Schindler for operation requirements.
- 27. Provisions for earthquake protection, dictated by building code, are required in various sections of the country.

#### Entrances

- 28. Hoistway walls must have a fire rating per ASME A17.1 Rule 2.1.1.1.
- 29. Furnishing, installing and maintaining the required fire rating of elevator hoistway walls, including the control spaces and also the penetration of fire wall by elevator fixture boxes (if applicable), is not the responsibility of the elevator contractor.
- 30 The interface of the elevator wall with the hoistway entrance assembly shall be in strict compliance with the elevator contractor's requirements.
- 31. Entrance wall and finished floor are not to be constructed until after door frames and sills are in place.
  - a. Where front walls are of reinforced concrete, the concrete openings must be minimum 16" (406 mm) wider [8" (203 mm) on each side] and 8" (203 mm) higher than the clear opening.
  - b. Where drywall or sheet rock construction is used for front walls, it shall be of sufficient strength to maintain the doors in true lateral alignment. Drywall contractor to coordinate with the elevator contractor.
  - Note: A support member must be provided for floor heights greater than 15'-0" (4572 mm) to support entrance header struts
  - c. Door frames are to be anchored to walls and properly grouted in place to maintain legal fire rating (masonry construction).
- 32. Filling and grouting around entrance by others.
- 33. Where openings occur, all walls and sill supports must be plumb.



Schindler is a member organization of the U.S. Green Building Council.

Schindler has received renewal to ISO 14001:2004 and ISO 9001:2008 certificates.





-DN-1015

#### **Chris Noel**

From: Sent: To: Subject: Attachments: Sheppard, Lisa <Sheppard@coj.net> Wednesday, June 26, 2013 12:46 PM Chris Noel RE: 2501 Riverside Avenue Property Scan 001.pdf

Had a brief moment...here is the page. Contributing structures have checks in the box. Double check the RE # to confirm.

Lisa Sheppard, AICP, LEED® AP Senior Historic Preservation Planner City of Jacksonville Planning and Development Department Ed Ball Building 214 North Hogan Street, Suite 300 Jacksonville, FL 32202 Phone: 904–255–7843 Fax: 904–255–7885 Email: <u>sheppard@coj.net</u> *The greenest building is the one already built... Historic Preservation is the ultimate recycling.* \*\*\*PLEASE NOTE THAT UNDER FLORIDA'S VERY BROAD PUBLIC RECORDS LAW, COMMUNICATIONS TO AND FROM CITY OFFICIALS ARE SUBJECT TO PUBLIC DISCLOSURE\*\*\*

From: Chris Noel [mailto:ChrisN@ttvarch.com] Sent: Wednesday, June 26, 2013 11:35 AM To: Sheppard, Lisa Subject: 2501 Riverside Avenue Property

Lisa,

Thanks a lot for your help a few minutes ago. If you could Email me a copy of the non-contributing list including the 2501 Riverside Property that would great, when you get a chance.

No rush.

Thanks again Lisa,

Christopher Noel, AIA Senior Vice President LEED™ Accredited Professional

TTVARCHITECTS, INC. 115 East Forsyth St. Jacksonville, FL 32202 USA www.ttvarch.com

T- 904.798.8333 F- 904.798.8335

Please consider the environment before printing this e-mail.

1

											•			•										i
							•			·												067 50 Q		) I I
																					•	Page 27		1
		•	. :				· · ·		· ·		•													1
										*			•				•		•					
operty Address	RIVERSIDE AV	<b>RIVERSIDE AV</b>	RIVERSIDE AV	RIVERSIDE AV	RIVERSIDE AV	<b>RIVERSIDE AV</b>	RIVERSIDE AV																	
Pr	2116	2247	2501	2791	2821	2916	2978	3220	3236	3240	3255	3315	3343	3405	3549	3636	3636	3636	3636	3654	3688			2
)er								•			•													
Real Estate Numb	090500 0000	000657 0000	090618 0000	077810 0000	078375 0000	077890 0000	0000 866220	078180 0000	079379 0000	079378 0000	079407 0000	079414 0000	079417 0000	079468 0000	079498 0000	091738 1002	091738 1008	091738 1006	091738 1004	091742 0000	091749 0000			
uting?	•			•	- - -	•		•														, August 27, 1997		
Contrib										- - -												. Wednesday		
												•	τ.					• .					·	















