Mod 7177 Comments – Bob Vincent

Mod# 7177, Comments now only. I will create these Alternate language later today.

The mod uses the words "perimeter overflowing edge" which is not defined in code.

Only the words "deck level overflow perimeter system" are used in code twice at 454.1.2.3- 5. and 454.1.9.6.2 and I think a definition is needed for the first, but not the latter.

Where these are installed, a building official approved handhold will be required to be installed per 454.1.6.5.3.1