

## Hilary Morgan <a href="mailto:hmorgan@trentcotney.com">hmorgan@trentcotney.com</a>

# FW: Seq. #68403 - Application for commercial pool permit

1 message

Frederick G. Humberstone <fhumberstone@pascocountyfl.net>
To: "hmorgan@trentcotney.com" <hmorgan@trentcotney.com>

Tue, Feb 2, 2016 at 9:42 AM

Cc: Donna Ritter <dritter@pascocountyfl.net>

Dear Ms. Morgan,

Please refer to my response to the applicants below which may answer all of your questions. If you have any further questions you are welcome to call me.

#### Frederick G. Humberstone, CBO

**Acting Building Official** 

**Building Construction Services** 

Pasco County Government Center

7508 Little Road

New Port Richey, FL 34654

Phone: 727-847-8127

Cell: 727-267-7476

E-mail: fhumberstone@pascocountyfl.net



From: Matt Call [mailto:matt.call@mylandteam.com]

**Sent:** Friday, January 29, 2016 11:18 AM

**To:** Frederick G. Humberstone

**Subject:** RE: Seq. #68403 - Application for commercial pool permit

Thanks for your assistance.

Matt Call

813-785-7959 (Cell)

From: Frederick G. Humberstone [mailto:fhumberstone@pascocountyfl.net]

**Sent:** Friday, January 29, 2016 10:53 AM

To: 'matt.call@mylandteam.com'; 'MRUBLE@ROCCHETTA-ADB.COM'; 'rick@gardnercollins.com';

'tsas@crsbuildingcorp.com'; 'jpiercy@crsbuildingcorp.com'

Cc: Donna Ritter; Don Rosenthal; Julius Gilliam

Subject: Seq. #68403 - Application for commercial pool permit

To everyone concerned,

I have personally reviewed the plans with the plans reviewer and resolved the problem. The problem arises where the perimeter pool gutter crosses the stairs into the pool.

The plans reviewer, Mr. Julius Gilliam, discovered a conflict in compliance between two requirements in Section 454 of the Florida Building Code for which he had hoped to obtain clarification from the engineer of record.

Paragraph **454.1.6.5.3.1.1** reads in part, "The gutter shall slope 2 inches (51mm), +/- 1/4 inch (+/- 6mm), from the lip to the drains."

The conflict arises where the gutter crosses the top step of the stairs.

Paragraph **454.1.2.5.3 Stairs** reads in part, "Treads and risers between the top and bottom treads shall be uniform to within  $\frac{1}{2}$  inch (12.7mm) in width and height. The riser heights shall be measured at the marked step edges and the differences in elevation shall be considered the riser heights."

I have personally red lined the 'Pool Step and Rail Detail' on sheet 4 of the submitted plans indicating the maximum ½ inch slope of the top step. The transition between the 2 inch gutter and the ½ inch tread slope can be achieved with the application of the pool finish. The building permit and reviewed set of plans are now ready to pick up.

I do apologize for any inconvenience and hope this issue could be better detailed in future plans submitted for review. My thanks to everyone for their cooperation.

### Frederick G. Humberstone, CBO

Acting Building Official

**Building Construction Services** 

Pasco County Government Center

7508 Little Road

New Port Richey, FL 34654

Phone: 727-847-8127

Cell: 727-267-7476

E-mail: fhumberstone@pascocountyfl.net





## "Bringing Opportunities Home"

The information transmitted, including attachments, is intended only for the person(s) or entity to which it is addressed and may contain material that is confidential, privileged and/or exempt from disclosure under applicable law. Any review, retransmission, dissemination or other use of, or taking of any action in reliance upon this information by persons or entities other than the intended recipient is prohibited. If you received this in error, please contact the sender and destroy any copies of this information. <u>Under Florida law, email addresses are public records</u>. If you do not want your email address released in response to a public-records request, do not send electronic mail to this entity. Instead, contact this office by phone or in writing.

CUSA18A7