RESPONSE TO REQUEST FOR ADDITIONAL INFORMATION BY PETITIONER

On 4-13-2020 the permit was extended based on construction progress based upon inspections done by the Threshold Inspector. According to the City's Inspection History, it accepted reports 1 thru 4 from the Threshold Inspector as proof of sufficient construction progress. See Attachments 5 and 11-14 of City Response

On September 10, 2021 the permit was again extended for construction progress again based on the Threshold Inspector. According to the City's Inspection History, inspection reports 1 thru 6 plus a report on the condition of the rebar from the Threshold Inspector were accepted as sufficient progress. Reports 5 and 6 are contained as Attachments 15 and 16 of the City Response. The report on condition of rebar is contained as Attachments 29-38 of the City Response

In each instance, the inspections and extensions were for some of the foundation elements required by the plans and in each instance that was sufficient to find sufficient construction progress. Attachment 5 of the City Response, Inspection History, verifies these extensions of the permit.

On March 9, 2022 at a requested inspection, the inspector documented 7 additional foundation pads, but refused to approve those pads, but gave no FBC based defects in the work that was inspected. See Attachment 5 of the City Response.