From: Myers, Paul T [mailto:MyersPT@cityofgainesville.org]
Sent: Thursday, August 4, 2022 1:20 PM
To: Sellers, Chip; Madani, Mo
Subject: ACCESSIBILITY ADVISORY COUNCIL - Swim Tech Gainesville – Waiver 581

[NOTICE] This message comes from a system outside of DBPR. Please exercise caution when clicking on links and/or providing sensitive information. If you have concerns, please contact your Knowledge Champion or the DBPR Helpdesk.

Dear Sirs,

RE: <u>Swim Tech Gainesville – Waiver 581</u> - 7010 NW 23rd Way B, Gainesville 32653

Just a footnote on this waiver.

This is an unpermitted Change of Use within the Jurisdiction of Gainesville where the applicant installed a swim pool, electrical & plumbing, and constructed a 4 foot high platform without the required permits or inspections. Application was made after the fact on 10/12/2021 (attached).

Currently the building permit is not approved / issued and the electrical and plumbing contractors have not made application for their scope of work.

Below are the outstanding issues with the last building review (6/2/2022) and the local health department (the applicant is working directly with HD – corrections may have been made).

Email	Status	Reviewer Comments
myerspt@cityofgainesville.org	Corrections Required	6/2/2022 - Previous corrections have not been resolved. 1) - Based on pictures provided, the deck and spa supports will be required to be inspected by a Florida Licensed Engineer and a signed and sealed compliance report submitted to the Building Department indicating the work complies with the Florida Building Code. 2) - The steps and handrails are not code compliant based on pictures and details submitted and are not accepted as built. A code compliant design is required and steps and accessible access to the spa deck. 3) - Per Florida Statute 553.505 Exceptions to applicability of the Americans with Disabilities Act.— Notwithstanding the Americans with Disabilities Act of 1990, private clubs are governed by this part., a private club is not exempt from accessibility.
Daniel.Wise@flhealth.gov	Corrections Required	Inspection on 8/2/2021 found the following issues: Heater needs to have by-pass plumbed in List of rules needed Depth markings needed recirculation pump called for a 3HP with appropriate piping size Flow set at 75 GPM

Thanks,

Paul

Paul T. Myers | Chief Plans Examiner City of Gainesville, Florida Gainesville Department of Sustainable Development Building Division | Desk 352-393-8560 | Cell 352-317-6508 Email <u>myerspt@cityofgainesville.org</u>