

July 20, 2023

Justin Wallace
BuildBlock Building Systems, LLC
9705 N Building Systems, LLC
Oklahoma City, Oklahoma 73114

Phone: 405-467-9161
Email: jwallace@buildblock.com

Subject: Code Compliance Research Report CCRR-1003 (BuildBlock®, BuildLock® and BuildRadius ICFs)

Dear Mr. Wallace,

CCRR-1003 Section 6.0 states that tests in accordance with ASTM E2634-18 have been conducted as supporting evidence. ASTM E2634-18 is referenced in the 2023 Florida Building Codes, however the scope of CCRR-1003 is currently the 2020 Florida Building Codes which references ASTM E2634-11(2015).

Intertek has conducted a review to compare ASTM E2634-11(2015) with ASTM E2634-18 and found that with the exception of additional requirements found in the 2018 edition, Section 6.3.2 – Gypsum Wallboard Attachment Test, there are no technical changes would affect compliance as reported in CCRR-1003.


Intertek has determined that the products reported in CCRR-1003, having been tested in accordance with ASTM E2634-18 also comply with ASTM E2634-11 (2015).

If you have any questions regarding this letter report, please do not hesitate to contact the undersigned.

Sincerely,

INTERTEK TESTING SERVICES NA, INC.

Reported by:



John Schachtner
Project Engineer- Evaluation Services
Building & Construction

Reviewed by:



Craig H. Wagner, P.E.
Chief Engineer
Building & Construction



This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only the sample tested. This report by itself does not imply that the material, product or service is or has ever been under an Intertek certification program.

