Page 1

☐ Original ☐ Update



HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE Version 5.0 3/19

Site#8	HI15009					
Field Date	06-29-2021					
Form Date	6-29-2021					
Recorder #	·					

Shaded Fields represent the minimum acceptable level of documentation. Consult the Guide to Historical Structure Forms for detailed instructions.							
Site Name(s) (address if none) 5137 n. Flo	rida Avenue		Multiple Listing (DHR only)				
Site Name(s) (address if none) 5137 n. Florida Avenue Survey Project Name Historical Seminole Heights			Sur	vey # (DHR only))		
National Register Category (please check one)	⊠ building □structure	☐ district ☐ site	object				
Ownership: □private-profit □private-nonprofit □priv	ate-individual private-nonsp	ecific city county	□state □federal	■Native American	☐foreign ☐unknown		
	LOCATION	& MAPPING					
Street Number Direction Street				ffix Direction			
	rida	Avei	nue				
Cross Streets (nearest/between) E.Frierson USGS 7.5 Man Name	Avenue and N. Fic	SCS Data	Plat or Other Mar	<u> </u>			
USGS 7.5 Map Name Tampa City / Town (within 3 miles) Tampa	In City Limits?	⊠ves ⊟no ⊟uni	riacoi Omerivia; mown Countv	J Hillsborouc	rh		
Township 295 Range $18E$ Section	/ 1/4 section: DN	W □SW □SE	□NE Irregular	r-name:			
Tax Parcel # 164741-0000		Landgrant			·		
Tax Parcel # 164741-0000 Subdivision Name SEMINOLE HEIGHTS		Block	12	Lot	19 & 20		
UTM Coordinates: Zone 116 121/ Easting	BLLLL North	ing L					
Other Coordinates: X: Y	: c	coordinate System &	& Datum				
Name of Public Tract (e.g., park)		 -					
	HIST	ORY					
Construction Year: 1922 □approximate		arlier 🗀 year list	ed or later				
Original Use Residence, private	F						
Current Use Restaurant		rom (year): 200					
Other Use Moves: Syes Inc Inchrown Date: _	7-31-1999 Original	rom (year):	lo (year	r):	•		
Alterations: Xyes Ino Inknown Date: _	7-31-2007 Nature	Converted to	Restaurant	venue			
Additions: ☐yes ☒no ☐unknown Date: _	Nature			1.	·		
Architect (last name first):		Builder (last name fi					
Ownership History (especially original owner, dates, p	rofession, etc.)						
Is the Resource Affected by a Local Preservation	on Ordinance? ⊠yes □	no □unknown D	escribe Contri	ibuting buil	ding locally		
	DESCR	IPTION					
Style Frame Vernacular	Exterior Plan	Rectangular		Number of	Stories 2		
Exterior Fabric(s) 1. Wood siding	2.		3.		Stories		
Roof Type(s) 1. Gable	2		3				
Roof Material(s) 1 Tile unspecified	2		3		<u></u>		
Roof secondary strucs. (domers etc.) 1	·		2	*****			
Windows (types, materials, etc.) wooden one over one							
wooden one over one							
Distinguishing Architectural Features (exterior or in	nterior ornaments)						
	,			· · · · ·			
Ancillary Features / Outhuildings (record outhuildings	ne major landenano fonturas	co continuation short if	nooded \	<u>.</u>			
Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)							
		 .					
DHR USE ONLY	OFFICIAL E	VALUATION_		DHR USE O	NLY		
NR List Date SHPO – Appears to meet of	criteria for NR listing: □yes	□no □insufficie	nt info Data				
KEEPER – Determined eliq	jible: □yes	□no	Date	<u></u>	Init		
	□a □b □c □d	(see National Regist	er Bulletin 15, p. 2)		· 		

DESCRIPTION (continued)						
Chimney: No Chimney Material(s): 1. Structural System(s): 1. Foundation Type(s): 1. Foundation Material(s): 1. Poured Condition Entrance (stylistic details)	2 2 crete Footing 2	2	3.			
Porch Descriptions (types, locations, roof types, et	c.)			····		
Condition (overall resource condition): Narrative Description of Resource	nt ⊠good □fair □do	eteriorated □ruinous				
Archaeological Remains				Check if Archaeological Form Completed		
R	ESEARCH METH	ODS (select all that a	pply)			
□FMSF record search (sites/surveys) □FL State Archives/photo collection □property appraiser / tax records □cultural resource survey (CRAS) □other methods (describe) ■Bibliographic References (give FMSF manuscrip	☐library research ☐city directory ☐newspaper files ☐historic photos ot # if relevant, use continuation she	□ building permits □ occupant/owner in □ neighbor interview □ interior inspection eet if needed)		□Sanborn maps □plat maps □Public Lands Survey (DEP) □HABS/HAER record search		
O)	PINION OF RESOU	JRCE SIGNIFICA	NCE			
Appears to meet the criteria for National Re Appears to meet the criteria for National Re Explanation of Evaluation (required, whether sin	gister listing as part of a dist	⊠ yes □no trict? ⊠ yes □no tif needed)	_	ent information ent information		
Area(s) of Historical Significance (see National 1. Archaeology-historic 2. Tourism		pories: e.g. "architecture", "ethni nning & developm	cheritage", "co 5. <u>Local</u> 6. Archit			
2. 10011500		ENTATION	0. <u>111 0111</u>			
Accessible Documentation Not Filed with the Document type	e Site File - including field notes	s, analysis notes, photos, plans a Maintaining organization File or accession #s Maintaining organization				
Recorder Name		Affiliation				
Recorder Contact Information		<u> </u>				

Required Attachments

- USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
- ② LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital <u>AND</u> hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.


5135 and 5137 N. Florida Avenue



125

250

500 7



Bob Henriquez, CFA

Hillsborough County Property Appraiser
This map is for assessment purposes only.
It is not a survey.